- 1. The power MOSFET device is a
- a. Current controlled unipolar device
- b. Voltage controlled unipolar device
- c. Current controlled bipolar device
- d. Voltage controlled bipolar device

ANSWER: Voltage controlled unipolar device

- 2. Unipolar modulation is generally used in
- a. AC AC converters
- b. AC DC converters
- c. DC AC converters
- d. DC DC converters

ANSWER: DC - DC converters

- 3. In a three phase converter, the number of notches per cycle is
- a. One
- **b.** Three
- c. Six
- d. Nine

ANSWER: Six

- 4. The switching function of semiconductor devices can be characterized with
- **a.** Duty ratio only
- **b.** Frequency only

- **c.** Duty ratio and frequency
- d. Duty ratio, frequency and time delay


ANSWER: Duty ratio, frequency and time delay

5. The quadrant operation of BJT is represented by





3.



- **a.** 1
- **b**. 2
- **c.** 3
- **d.** 4

ANSWER: 2

- 6. What is the general ratio of the cross sectional area of the two metals used in the A.C.S.R conductors?
- **a.** 1:8
- **b.** 1 : 4

- **c.** 4 : 3 **d.** 2 : 1
- **ANSWER: 1:4**
- 7. In India, which types of poles are commonly used for distribution?
- a. Wooden poles
- **b.** RCC poles
- c. Steel poles
- d. Both (b) and (c)
- e. None of these

ANSWER: Both (b) and (c)

- 8. To prevent rotting oil the wooden poles which oil is impregnated to it?
- a. Kerosene oil
- **b.** Mineral oil
- c. Creosote oil
- d. All of these

ANSWER: Creosote oil

- 10. What is the main purpose for guy wire?
- a. Supports the pole
- **b.** Protects against the surges
- c. Provides emergency earth route
- d. All of these

ANSWER: Supports the pole

- 11. Conductor sag should be kept
- **a.** Minimum
- **b.** Maximum

- c. Zero
- d. None of these

ANSWER: Minimum

12. Which line represents the tension in the given graph?




Fig 2.2: Temperature Vs Tension and Sag

- a. I
- **b.** II
- c. III
- d. IV

ANSWER: II

13. The number of discs in a string of insulators for 400 kV ac over head transmission line lies in the range of

- **a.** 32 33
- **b.** 22 23
- **c.** 15 16
- **d.** 9 10

ANSWER: 22 - 23

14. What is switchgear?

a. An apparatus used for switching, controlling and protecting the electrical circuits and equipments.

PRACTICE SET:- 3

- **b.** It detects the faults only.
- c. It corrects the faults only.
- d. All of the above.

ANSWER: All of the above.

- 15. Which material is used for the manufacture of bus bars?
- a. Aluminium rods.
- b. Copper rods.
- c. Any conducting material.
- d. Made of silver.

ANSWER: Copper rods.

- 16. Which among these are the main characteristics of a fuse element?
- a. Low melting point
- **b.** High conductivity
- c. Least deterioration due to oxidation
- **d.** All of the above

ANSWER: All of the above

17. What is fusing factor?

- a. The ratio of current rating of the fuse to the minimum fusing current
- b. The ratio of minimum fusing current to the current rating of the fuse
- c. The ratio of maximum fusing current to the current rating of the fuse
- d. The ratio of minimum fusing current to the voltage rating of the fuse

ANSWER: The ratio of minimum fusing current to the current rating of the fuse

- 18. Field in case of rod gaps and sphere gaps are
- a. Uniform, uniform
- **b.** Uniform, non-uniform
- c. Non-uniform, uniform
- d. Non-uniform, non-uniform

ANSWER: Non-uniform, uniform

- 19. In Breakdown tests, the tests voltages required for these tests are usually of the order of
- **a.** 0 10 kV
- **b.** 20 50 kV
- **c.** 50 100 kV
- **d.** 100 200 kV

ANSWER: 50 - 100 kV

- 20. Which among the following is not an example of impregnants?
- a. Mineral oil
- **b.** Chlorinated diphenyl
- **c.** Vegetable oils
- **d.** None of these

ANSWER: None of these

21. In a three phase induction motor, the mechanical load should be such that the equivalent load resistance referred to stator is equal to the

- a. Total leakage reactance of the motor referred to stator
- **b.** Total leakage reactance of the motor referred to rotor
- c. Total leakage impedance of the motor referred to stator
- d. Total leakage impedance of the motor referred to rotor

ANSWER: Total leakage impedance of the motor referred to stator

- 22. When an induction motor is working under loaded condition, its induced voltage will
- a. Leads the magnetic flux by 90 degree
- b. Lags the magnetic flux by 90 degree
- c. Lags the magnetic flux by 30 degree
- d. In phase with the magnetic flux

ANSWER: Lags the magnetic flux by 90 degree

- 23. The performance of induction motor is effected by the harmonics in the
- a. Space variation of impressed voltage
- **b.** Time variation of impressed voltage
- c. Space variation of impressed current
- d. Time variation of impressed current

ANSWER: Time variation of impressed voltage

- 24. The tooth or slot harmonics in an induction motor is caused due to
- a. Variation of air gap reluctance
- **b.** Leakage flux
- c. Non sinusoidal nature of input voltage
- d. None of these

ANSWER: Variation of air gap reluctance

25. The air gap flux of induction motor does not contain

- **a.** 2nd harmonics
- **b.** 3rd harmonics
- c. 5th harmonics
- d. 7th harmonics

ANSWER: 3rd harmonics

26. At start, the slip of the induction motor is

- **a.** 1
- **b.** 0
- **c.** 0.5
- d. None of these

ANSWER: 1

- 27. The starting torque developed in the d.c. series motor and in d.c. shunt motor is
- a. High, low
- b. High, moderate
- c. Moderate, low
- d. Moderate, high

ANSWER: High, moderate

- 28. The speed armature current characteristics of a d.c. series motor is
- a. Rectangular hyperbola
- **b.** Linear
- **c.** Parabolic
- d. Parabolic till saturation and then linear

ANSWER: Rectangular hyperbola

- 29. D.C. series motors are used in electric traction. What happens to the speed and current of d.c motor if there is sudden slight drop in the mains voltage?
- a. Speed decreases and current also decreases
- **b.** Speed decreases and current increases

- c. Speed increases and current decreases
- d. Speed decreases and current remains same

ANSWER: Speed decreases and current remains same

30. If a resistance is added in series with the field winding of d.c. shunt motor, then its

- **a.** Both speed and torque decreases
- **b.** Both speed and torque increases
- c. Speed decreases, torque increases
- **d.** Speed increases, torque decreases

ANSWER: Speed increases, torque decreases

- 31. Electric pressure is also called
- a. resistance b. power c. voltage d. energy

Ans-c

32 The substances which have a large number of free electrons and offer a low resistance are called

- a. insulators
- b. inductors
- c. semi-conductors
- d. conductors

Ans-d

33. Out of the following which is not a poor conductor?

- a. Cast iron
- b. Copper
- c. Carbon
- d. Tungsten

Ans-b

- 34. Out of the following which is an insulating material?
- a. Copper
- b. Gold
- c. Silver

SCIENCE STOPPERS

PRACTICE SET:- 3 | SSC JE | DMRC JE | UPPCL JE

d. Paper

Ans-d

35. The property of a conductor due to which it passes current is called

- a. resistance
- b. reluctance
- c. conductance
- d. inductance

Ans-cc

36 . Conductance is reciprocal of

- (a) resistance
- (b) inductance
- (c) reluctance
- (d) capacitance

Ans-a

37. The resistance of a conductor varies inversely as

- (a) length
- (b) area of cross-section
- (c) temperature
- (d) resistivity

Ans-b

38. With rise in temperature the resistance of pure metals

- (a) Increases
- (b) decreases
- (c) first increases and then decreases
- (d) remains constant

Ans-a

39. With rise in temperature the resistance of semi-conductors

- (a) decreases
- (b) increases
- (c) first increases and then decreases
- (d) remains constant

Ans-a

40. The resistance of a copper wire 200 m long is 21 Q. If its thickness (diameter) is 0.44 mm, its specific resistance is around

- (a) 1.2 x 10~8 Q-m
- (b) 1.4 x 10~8 Q-m
- (c) 1.6 x 10""8 Q-m
- (d) 1.8 x 10"8 Q-m

Ans-c

41. Three resistances of 10 ohms, 15 ohms and 30 ohms are connected in parallel. The total resistance of the combination is

PRACTICE SET:- 3

- (a) 5 ohms
- (b) 10 ohms
- (c) 15 ohms
- (d) 55 ohms

Ans-a

- 42. An instrument which detects electric current is known a
- (a) voltmeter
- (b) rheostat (c)

wattmeter

(d) galvanometer

Ans-d

- 43. In a circuit a 33 Q resistor carries a current of 2 A. The voltage across the resistor is
- (a) 33 V
- (b) 66 v
- (c) 80 V
- (d) 132 V

Ans-b

- 44. A light bulb draws 300 mA when the voltage across it is 240 V. The resistance of the light bulb is
- (a) 400 ohm
- (b) 600 ohm
- (c) 800 ohm
- (d) 1000 ohm

Ans-c

SCIENCE STOPPERS

- 45. The resistance of a parallel circuit consisting of two branches is 12 ohms. If the resistance of one branch is 18 ohms, what is the resistance of the other?
- (a) 18 ohm
- (b) 36 ohm
- (c) 48 ohm
- (d) 64 ohm

Ans-b

- 46. Four wires of same material, the same cross-sectional area and the same length when connected in parallel give a resistance of 0.25 ohm. If the same four wires are connected is series the effective resistance will be
- (a) 1 ohm
- (b) 2 ohm
- (c) 3 ohm
- (d) 4 ohm

Ans-d

- 47. A current of 16 amperes divides between two branches in parallel of resistances 8 ohms and 12 ohms respectively. The current in each branch is
- (a) 6.4 A, 6.9 A
- (b) 6.4 A, 9.6 A
- (c) 4.6 A, 6.9 A
- (d) 4.6 A, 9.6 A

Ans-b

- 48. Current velocity through a copper conductor is
- (a) the same as propagation velocity of electric energy
- (b) independent of current strength
- (c) of the order of a few micro second
- (d) nearly 3 x 108 m/s

Ans-c

- 49. Which of the following material has nearly zero temperature co-efficient of resistance?
- (a) Manganin
- (b) Porcelain
- (c) Carbon
- (d) Copper

Ans-a

- 50. You have to replace 1500 ohm resistor in radio. You have no 1500 ohm resistor but have several 1000 ohm ones which you would connect
- (a) two in parallel
- (b) two in parallel and one in series
- (c) three in parallel

SCIENCE STOPPERS

PRACTICE SET:- 3 | SSC JE | DMRC JE | UPPCL JE

(d) three in series

Ans-b